## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventors: Necdet Uzun

Assignee: Cisco Technology, Inc.

Title: FAULT TOLERANT NETWORK TRAFFIC MANAGEMENT

Application No.: 09/843,021 Filing Date: April 25, 2001

Patent No.: 7,142,504 Issue Date: November 28, 2006

Group Art Unit: 2616 Examiner: Ian N. Moore

Docket No.: CIS0159US Confirmation No.: 7231

Austin, Texas June 22, 2007

of

ATTN: Certificate Of Correction Branch Of The Patent Issue Division COMMISSIONER FOR PATENTS P. O. Box 1450 Alexandria. VA 22313-1450

## REQUEST FOR ENTRY OF CERTIFICATE OF CORRECTION

Sir:			
	Pleas	Please enter the enclosed Certificate of Correction (PTO Form 1050) in the above patent The errors sought to be corrected were made by	
	The		
	$\boxtimes$	the Patent and Trademark Office. Thus, no fee is required for the Certificate	
		Correction pursuant to 37 CFR §1.322.	

Applicant(s) (at least in part). See next section for explanation. The appropriate fee under 37 CFR §1.323 has been authorized below.

Please correct the errors, as noted in the enclosed Certificate of Correction, made by the USPTO.

All inquiries concerning this request should be directed to the undersigned attorney at (512) 439-5090.

Respectfully submitted,

Jonathan N. Geld Attorney for Applicant(s)

Reg. No. 44,702 Telephone: (512) 439-5090 Facsimile: (512) 439-5099

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,142,504 B1

ISSUE DATE : November 28, 2006

INVENTOR(S) : Necdet Uzun

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Claim 11 should be dependent on Claim 10 not Claim 1, therefore: At column 12, line 1, please delete "claim 1" and insert --claim 10--

PRINTER'S

MAILING ADDRESS OF SENDER

CAMPBELL STEPHENSON LLP

4807 Spicewood Springs Road Building 4, Suite 201 Austin, Texas 78759

Telephone: 512-439-5080 • Facsimile: 512-439-5099

PATENT NO. 7,142,504 B1 No. of add'l copies: 0 @ 50¢ per page

